



# INSPECTION REPORT

<b>PROJECT'S NAME :</b> SYS PRIMERBOND (Standard)	<b>CONTRACTOR :</b> CSH	<b>SHOP :</b> Siam Yamato Steel <b>DATE :</b> 29/1/2019
--	----------------------------	--

**PAINTING SPEC :**

1 <sup>st</sup> Coat	Multix Primer Reddish Brown	40 microns
2 <sup>nd</sup> Coat	Multix Primer CS-650 Black	40 microns
3 <sup>rd</sup> Coat		microns
4 <sup>th</sup> Coat		microns
<b>Total</b>		<b>80 microns</b>

PIECE MARK	WEATHER CONDITION	POSITION	D.F.T. (MICRONS)										AVERAGE (Microns)
			A	B	C	D	E	F	G	H	I	J	
Beam	NO. OF COAT		81	76	84	82	87	88	81	83	77	110	84.9
	2nd.Coat.		85	91	103	86	97	87	87	108	97	76	91.7
	AMB.. TEMP.		108	79	93	101	85	97	97	107	110	103	98.0
	33.4C°		109	93	108	79	81	96	97	103	97	90	95.3
	SURFACE TEMP.		86	89	79	92	77	84	80	108	79	100	87.4
	36.2C°		89	78	101	99	84	99	78	78	102	108	91.6
	% RH.		107	99	103	107	93	101	78	87	110	108	99.3
	63.4		94	83	91	91	108	99	94	92	87	90	92.9
	DEW POINT		93	89	91	110	83	100	104	105	93	100	96.8
	25.2C°		93	89	106	92	107	88	85	100	94	94	94.8
WEATHER COND.		92	107	102	91	86	107	93	103	106	87	97.4	
good		85	82	91	75	92	87	108	88	85	107	90.0	

**ROUGH SKETCH OF MEASUREMENT POSITION**

93.3



**REMARK :**

SPEC D.F.T.            **80**    MICRONS  
CHECK D.F.T.        **93.3**   MICRONS

**CHK'D**

Y. Apinan /TCP